

School Building Infrastructure & Project Management Stewardship Report



Prepared by:

Thomas Lamb
Chief Operations Officer

Joseph Barbarotta Executive Director of Facilities Management



- 1. Construction Grant Updates
- 2. Commissioning Schedule Updates
- 3. School & Building Infrastructure Project Planning
- 4. Energy Management and Sustainability
- 5. Indoor Air Quality Program Update
- 6. Work Order Management

Construction Grants Update



Sound School

Filtration System

System has been ordered

In preparation for install district trade staff will complete by week of 7/12:

- Trench and installed floor drain
- Acid treatment and painting of floor
- Boisvert completed reclaiming refrigerant from 18 condensing units that serve the fish production.

Roof Replacement

Contract to Silver Petrucelli for creating the bid specifications is moving through signature process and will be sent to vender week of 7/12.

Construction Grants Update



ESSERII Grant

Bottle Filling Station

- One unit has has been ordered to ensure proper install and test unit.
- Connections at all schools are different and will need to determine what unit will fit in each location.
- 2 Units per school
 - One unit at the nursing / administration area
 - One unit in or near the cafeteria

BMS System Upgrades

Upgrades to Tritium are in process at:

- Martinez School—50% Complete
- Nathen Hale—80% Complete
- Daniels School—20% Complete

Commissioning Schedule Update



Gilbaine Services has officially concluded services to the Board of Education

Electronic project files for all projects have been turned over to COO

AMENDMENTS IN PROCESS AND WATING:

Grant/Mayo:

- Giordano A#18 (awaiting signatures from BOE since May 18th)
- SSRCx A#3 (same as above)
- CAPO's from BOE accounting (sent weekly emails requesting starting April 20th)
- As you know SCP processes differently than BOE

Gilbaine will provide:

Templates and instructions for:

- 49F (instructions only)
- Make packages of items sent to Corp Counsel for execution and approval including my "submission checklist"
- Get Giordano A18 and SSRCx A3 through to Corp Counsel and approved
- Clean up open and non-audited school files on server. I've done older files.
- Fusco A#20 Close out amendment after Mechanical Contractor is closed out (BOE will need to process)

COMPLETED TEMPLATES: (as of today)

- Template of 49F's for BOE and Citywide Committee
- SSRCx A1 (ESUMS) amendment for submittal to F&O and BOE for approval along with instructions including the memos. (Need Bonding Company approval)



Hot Water Tank Replacements

Lincoln Bassett School

- Tank is leaking and failure is imminent
- Awaiting PO for design of system

Bishop Woods School

- Tank has failed
- Small Temporary is in place
- May not meet the needs of school at full capacity

Additional locations will be identified and prioritized as part of the long term facilities study



Swimming Pool Equipment Upgrades, Repairs or Replacements

Career School

- 16 floor drains around pool have been replaced.
- Pumps are no longer serviceable and require replacement
- Ceiling above pool and walls are damaged and need to be scraped and painted
 - Project has been band and has a cost of \$174,320
- Tile Flooring around pool is damaged and needs to be re-grouted
- Sand filter is not functioning and requires replacement.
- Facilities Team is working with city purchasing to award bid
- No work has started to-date

Conte School

- Assessment for structure of pool 7/8
- Pool closed and drained for safety
- Sand Filter media is in need of replacement
- Project bid and has a cost of \$23,700
- Need to identify funding source

Cross School

- Acid washing and re-grouting of pool area tile
- Estimated cost of \$50,000
- Need to Identify Funding Source



Swimming Pool Equipment Upgrades, Repairs or Replacements

Cross School

- Acid washing and re-grouting of pool area tile
- Estimated cost of \$50,000
- Need to Identify Funding Source

Hillhouse School

- Pool Surface in need of re-grouting
- Estimated cost of \$33,597.00
- Need to Identify funding source

Martinez School

- Removal and replacement of dehumidification system that is beyond serviceable life and no longer functioning.
- Bid has been awarded for engineering services to create scope of work
- Estimated cost of replacement is \$400,000.00



Boiler Replacements

Fair haven and Wexler School

- Boilers have ben on Order since January
- Approximate delivery 4 to 6 week out
- BioServ Plumbing is performing work at Wexler
- SK Mechanical is performing work at Fairhaven

Boiler Replacements next to schedule

- Hillhouse
- Nathen Hale
- Lincoln Bassett

Additional locations will be identified and prioritized as part of the long term facilities study



Development of District Rolling Capital Improvement Plan

Plan Development

- Long Term Facilities Study
- Building Inventory with age of building and last major renovation
- Asset Inventory of all major building systems and date of install
- Assessment and prisonization of all district building assets based on building Age:
 - Roofs
 - Parking lots and Side Walks
 - Building Envelops
 - Heating Systems
 - Cooling Systems
 - Fire Suppression Systems
 - Fire Alarm Systems

Additional locations will be identified and prioritized as part of the long term facilities study

Energy Management and Sustainability



LED Lighting Upgrades Scheduled for 21/22

- Hill Regional Career
- Clinton Avenue School
- Troup
- King Robinson School
- Martinez (if funding allows)

End of Year Electricity and Natural Gas Report

 Currently gathering end of year data to compile report next meeting

Fuel Cell

- Need to determine what next steps will be.
- Struggling to get vendor to respond

Indoor Air Quality Program Update



Filter Changes

MERV 13 and MERV 8 Filter Change Process

- Change process takes about 4 to 6 weeks
- Current Bid is out to supply filters for the next scheduled change
- 2 Filter Changes per year at approximately \$150,000 each
- Filter replacement schedule developed for every six months in each school

Filter Checks and Balances

- Filter install process / Date and photograph filters
- Inspection procedures developed for custodial supervisors and managers including signatures.
- Air Quality Inspection survey will be conducted with the facilities
 leadership, the building manager and the school leadership each month.